PB-216 854

PLUMBING AND PUBLIC HEALTH: A BIBLIOGRAPHY

Public Health Service
Washington, D. C.

1 July 1948

DISTRIBUTED BY:

NTIS

National Technical Information Service
U. S. DEPARTMENT OF COMMERCE
5285 Port Royal Road, Springfield Va. 22151

Paul D. Haney

PB 216 854

LIBRARY

Environmental Protection Agency
5555 Ridge Ave., Cincinnati, O. 45213

PLUMBING AND PUBLIC HEALTH

A Bibliography

FEDERAL SECURITY AGENCY

Public Health Service
Division of Hospital Facilities
Division of Sanitation

July 1, 1948

Reproduced by
NATIONAL TECHNICAL
INFORMATION SERVICE
U S Department of Commerce
Springfield VA 22151

PLUMBING AND PUBLIC HEALTH

Bibliography*

(Corrections of the material contained herein and additional references to related material will be appreciated and may be sent to the address given on the title page.)

ANONYMOUS:

1. Life is a Priceless Gift. The Sanitary Institute, St. Louis, Mo. Pamphlet, 3 pp.

2. Water Supply Cross-Connection Rules of Ontario Board of Health. Engineering News-Record, 87:1:374 (September 1, 1921).

3. Typhoid Fever and Cross-Connections in Illinois. Engineering News-Record, 94:13:526 (March 26, 1925).

4. Plumbing, Heating, Ventilating and Public Health. Domestic Engineering, 118:1:53 (January 1, 1927); 118:6:21 (February 5, 1927)

5. American Society of Sanitary Engineering Holds Spirited Convention in Detroit. Plumbing and Heating Contractors Trade Journal, 87:6:46 (September 15, 1929).

6. Sanitary Engineers Hold 24th Annual Meeting. Domestic Engineering, 128:6:159 (September 21, 1929).

7. Demonstration of Hospital Plumbing - Cross-Connection Draw Attention of Thousands. Plumbers and Contractors Trade Journal, 87:10:49 (November 15, 1929).

8. Pool Cross-Connection Outlawed. Muncipal Sanitation, 1:336 (June 1930)

9. Contamination of Water Systems by Consumers' Water Uses. Engineering News-Record, 105:4:141 (July 24, 1930).

10. Constructive Program of Research and Education Advanced at A.S.S.E. Meeting. Plumbers and Contractors Trade Journal, 89:36 (September 1, 1930).

11. Water System Contamination. Canadian Engineer, 59:15:534 (October 7, 1930).

12. See 3,000,000 Remodeling Jobs in Cross-Connection Menace. Plumbing and Heating Contractors Trade Journal, 92:11:56 (March 15, 1932).

*As of July 1, 1948.

13. Cross-Connection Preventive Built Into Hospital Plumbing, Plumbing and Heating Contractors Journal, 93:6:35 (September 1932).

14. N.A.M.P. Files Plumbing Health Brief in Support of Its Code. Plumbing and Heating Trade Journal, 95:6:42 (December 1933).

15. Trace Amebic Dysentery to Bad Plumbing. Illinois Master Plumber, 19:7 (February 1934).

16. Chicago Will Inspect Old Buildings for Faulty Plumbing. Illinois Master Plumber, 19:10 (February 1934).

17. Amebiasis Outbreak Due to Defective Plumbing in Hotels. Municipal Sanitation, 5:98 (March 1934).

18. Chicago Dealers War on Handyman Plumbing. Illinois Master Plumber, 19:9 (March 1934).

19. Plumbing and Health (Editorial). Hygeia, 12:198 (March 1934).

20. Murphy to Urge N.A.M.P. on Amebiasis at Convention. Plumbing and Heating Trade Journal, 96:5:17 (May 1934).

21. Louisiana-Mississippi Association Approves Back-Siphonage Guard. Plumbing and Heating Trade Journal, 96:6:53 (June 1934).

22. Stop Cross-Connections with Police Help. Domestic Engineer, 142:51 (June 1934).

23. Dysentery Epidemic Detailed Before Waterworks Body. Engineering News-Record, 112:24:779 (June 14, 1934).

24. Back-Siphonage - Its Cause and Cure. The Valve World, 31:3:98 (July 1934).

25. Cross-Connection Regulation. Water Works Engineering, 87:26:1156 (October 17, 1934).

26. Cross-Connections Present Danger of Pollution. Municipal Sanitation, 5:348 and 384 (October and November 1934).

27. The Chicago Breaker Tests. Domestic Engineering, 145:40 (January 1935).

28. Back Siphonage. Illinois Master Plumber, 20:14 (January 1935).

29. The Problem of Back-Siphonage. Skyscraper Management, 20:3:10 (March 1935).

30. Closet Bowl Back-Siphonage Tests Staged in Cincinnati. Plumbing and Heating Trade Journal, 98:3:42 (March 1935).

31. Importance of Plumbing is Recognized by Congress. Domestic Engineering, 145:70 (June 1935).

32. Reasons for Plumbing Codes. Domestic Engineering, 146:3:77 (September 1935).

33. Sanitary Engineers Discuss Cross-Connections. Municipal Sanitation, 6:296 (October 1935).

34. What's Being Done in Wisconsin. Domestic Engineering, 146:5:61 (November 1935).

35. St. Louis Research Laboratory Spreads the Gospel of Sanitation. Plumbing and Heating Trade Journal, 99:6:74 (December 1935).

36. Hotel Plumbing Revamped for Water Works Convention. Engineering News-Record, 116:25:879 (June 18, 1936).

37. Maryland-Delaware Conference Reviews Sewage Treatment Problems. Municipal Sanitation, 7:210 (June 1936).

38. Texas (San Antonio) Exhibit. Domestic Engineering, 148:2:123 (August 1936).

39. Privies and Bad Plumbing Doomed in Louisville Health Crusade. Plumbing and Heating Trade Journal, 101:3:38 (September 1936).

40. Health Hazards in Modern Plumbing in Public Buildings. Journal, Missouri State Medical Association, 33:365 (September 1936).

41. Survey Bares Plumbing Faults. The Ladle, 12:13 (September 1936).

42. Water Closets, Flushing Devices and Back-Siphonage. Plumbing and Heating Trade Journal, 101:4:66 (October 1936).

43. Chicago Activities. (Excerpts from Report on Progress made in Chicago Area to Eliminate Cross-Connections). Domestic Engineering, 148:4:130 (October 1936).

44. Back-Siphonage Research Undertaken by the Industry. (Description of research undertaken by plumbing industry and others). Architectural Record, 81:43 (January 1937).

45. Lessons for Sanitary Engineers Provided by Dysentery Epidemic. Municipal Sanitation, 8:175 (March 1937).

46. Sanitary Fixtures for Schools. Architectural Record, 81:46 (April 1937).

47. Texas (Houston) Exhibit. Domestic Engineering, 149:148 (May 1937).

48. Cross-Connections. Domestic Engineering, 149:87 (May 1937).

49. Outstanding Features of New York City's New Plumbing Code. Domestic Engineering, 150:69 (March 1938).

50. Address on Research. National Association of Master Plumbers, Pamphlet, 9 pp. (June 6-9, 1938).

51. Safety in Plumbing Systems. Architectural Record, 84:71 (August 1938).

52. The Issue of the Hour. Plumbing and Heating Business, 1:1:15 (September 1938).

53. Pollution Dangers Within Buildings and Their Control. Water Works Engineering, 91:1502 (November 9, 1938

54. Techniques for Sanitarians. The Sanitarian, 1:7:15 (December 1938)

55. Where to Look for Cross Connections or Back Siphonage. The Pennsylvania Master Plumber, 1:3:18 (December 1938).

56. An Ordinance for the Regulation of Cross Connections and the Elimination of Back Siphonage. (Los Angeles). The Sanitarian, 1:8:22 (January 1939)

57. Plumbing Amendments Passed (New York City). The Master Plumber, 9:2:22 (February 1939).

58. The Lesson of the Michigan Plumbing Tragedy. Plumbing and Heating Business. 1:8:11 (April, 1939).

59. Detroit Proves Its. Domestic Engineering, 154:1:32 (July 1939).

60. Cross Connections and Back Siphonage in Plumbing Fixtures. The Sanitarian, 2:2:7 (July 1939).

61. Approved Vacuum Breakers. The Master Plumber. 9:8:12 (August 1939); 9:9:12 (September 1939); 9:10:12 (October 1939); 9:11:21 (November 1939); 9:12:21 (December 1939) and 10:1:18 (January, 1940).

62. What is a Cross Connection? Domestic Engineering, 154:4:82 (October 1939).

63. Products and Practice. Architectural Forum, 71:4:20 (October 1939).

64. What Sanitation Standards for Convention Hotels: Water Works Engineering, 92:26:1605 (December 20, 1939).

65. Cross Connections in Plumbing Systems, Journal of Milk Technology, 2:4:192 (July 1939).

66. The Regulation of Plumbing and Use of the Sanitary Sewers, The Municipality, 35:129 and 193 (July 1940).

67. Plumbing and Public Health. Public Health Bulletin No. 256, Government Printing Office, Washington, D. C.

68. Plant Cross Connection Endangered Factory Workers. Water Works Engineering, 96:891 (August 11, 1943).

69. Cross Connection Elimination in Los Angeles, California. Water Works Engineering, 98:402 (April 1945).

70. Practicies of City Water Departments in Regard to Cross Connections Public Works, 77:22 (March 1946).

71. Guarding Against Back Siphonage. Water Works Engineering, 100:363 (April 2, 1947).

72. Cross Connection Hazards at Sewage Plants. Sewage Works Engineer, 18:534 (October 1947).

73. Cross Connections and Back Siphonage Problems. (Paper Presented to Water Supply Section, School of Government, University of Southern California, 1940).

74. Cross Connections in Plumbing and Water Supply Systems, Wisconsin State Board of Health and University of Wisconsin, 1936.

75. Vacuums in Potable Water Supplies From Sanitary Inspectors Manual, Louisiana State Board of Health, Plumbing-Drainage Topics, 4:11 (November 2, 1943).

76. Back Flow and Water Pollution. Plumbing and Heating Journal, 108:1:33 (January 1940).

77. Cross Connection Hazards from Refrigerating Equipment. Engineering News-Record, 130:12:94 (March 25, 1943).

78. Cross Connection Spreads Disease in Shipyard. Plumbing and Heating Business, 7:3:94 (March 25, 1943).

79. Dangerous Cross Connections Discovered in Brookline School. Progress, 6:3:27 (October 1944).

80. Demonstration Given at New Bedford Plumbing Laboratory. Progress, 6:12:12 (August 1944).

81. Dysentery Bacillary, USS Louisville, United States Naval Medical Bulletin, 40:506 (April 1942).

82. Health Safeguards in Plumbing Exhibited at Fair. The Ladle, 16:8:8 (August 1940).

83. Hospital Plumbing. The Sanitarian, 3:90 (September 1940).

84. Los Angeles Laboratory. Domestic Engineering, 154:6:49 (December 1939).

85. Plumbing Industry Finds Means to Guard Against Back Siphonage. Maryland Master Plumber, 19:1:6 (July 1944).

86. Standard Backflow Prevention Methods Proposed. Plumbing and Heating Business, 3:2:37 (September 1940); 3:3:35 (October 1940).

87. Where the Water Supply and Public Health are Protected. Plumbing and Heating Business, 2:9:28 (April 1940).

88. Where to Look for Cross Connections or Back Siphonage. The Yankee Plumber, 8:11:16 (November 1940).

89. Where to Look or Cross Connections or Back Siphonage. The Pennsylvania Master Plumber, 1:3:18 (December 1938).

90. Vacuums in Potable Water Supplies. Maryland Master Plumber, 18:6:5, (December 1943).

91. Unsafe Connections to Water Supplies. State Department of Health, Minnesota, Manual of Water Supply Sanitation, Section XIII (1941).

92. Plumbing, New York City Department of Health, (Report of the Department of Health at the New York World's Fair for the Period Ending October 31, 1939). (February 1940).

93. Bad Plumbing is Presumed Source of New York Epidemic. Plumbing and Heating Business, 3:6:12 (January 1941).

94. Plumbing and Public Health. Plumbing and Heating Business, 3:6:16 (January 1941).

95. What to Tell Your Customers About Backflow. Plumbing and Heating Business, 3:7:19 (February 1941).

96. A Review of the New American Standards for Air Gaps and Backflow Preventers for Plumbing Systems. Plumbing and Heating Business, 6:2:22 (September 1943).

97. Back Flow Hazards Increased During War Giving Disease to Thousands. Plumbing and Heating Business, 7:10 (May 1945).

98. In Spite of Rigid Plumbing Codes Polluted Water is Being Delivered at the Faucets. Plumbing and Heating Journal, 118:10:97 (October 1947).

99. Home Made Apparatus Shows 15,000 People How to Dodge Plumbing Hazards. Plumbing and Heating Business, 9:5:32 (December 1946).

100. Placing Vacuum Breakers in Existing Systems. Plumbing and Heating Journal, 110-111:1:21 (January 1941).

101. Cross Connections and Back Siphonage Connections Under War Conditions, American Journal of Public Health, 35:6:637 (June 1945).

102. Plumbing: The Sanitation Manual. New York State Restaurant Association, Inc., p. 13, (1948).

103. Telling the World How Faulty Plumbing Invites Disease. Plumbing and Heating Business, 5:1:22 (August 1940).

104. American Public Health Association Considers Plumbing Hazards. Plumbing and Heating Journal, 113:11:20 (November 1940).

105. Discovering Plumbing Defects: A Great Community War Time Service. Plumbing and Heating Journal, 114:1:24 (January 1943).

106. New Plumbing Standards to Keep Drinking Water Pure. Plumbing and Heating Journal, 112(2):9.36 (September 1943).

107. Searching for a Relationship Between Polio and Faulty Plumbing. Plumbing and Heating Journal, 116:3:60 (March 1946).

108. Plumbing Industry Traces Polio to Poor Sanitation. Domestic Engineering, 164:5:82 (November 1944).

109. Plumbing: Health and Civilian Defense. Domestic Engineering, 160:5:45.

110. Water: Hot or Cold, Is a War Material. Domestic Engineering, 162:2:62 (August 1943).

111. Polio Research: New Avenue of Approach. Domestic Engineering, 162:2:59 (July 1943).

112. Polio Proved to be Water-Borne. Domestic Engineering, 162:4:64, (October 1943).

113. Tragic Polio: Death of a Child Shows Relation of Disease to Faulty Plumbing. Domestic Engineering, 162:6:61 (December 1943).

114. What Our Industry Can Do To Stop Spread of Polio. Domestic Engineering, 163:6:79 (June 1944).

115. Proof: Polio In water. Domestic Engineering, 168:1:82 (July 1946).

116. Polio by Back Siphonage. Domestic Engineering, 168:2:82 (August 1946).

117. Florida Polio Cases. Domestic Engineering, 168:3:100 (September 1946).

118. Disease Virus Back Siphoned Thru Plumbing. Domestic Engineering, 168:4:116 (October 1946).

119. Florida Polio Study. Domestic Engineering, 168:4:118 (October 1946).

120. Hospital Plumbing. Domestic Engineering, 168:5:102 (November 1946).

121. How Disease Flows by Back Siphonage in Plumbing System. Domestic Engineering, 168:6:114 (December 1946).

122. Plumbing Hazards and How to Correct Them. Domestic Engineering, 170:4:102 (October 1947).

123. Role of Sewage Back-ups is Shown, Domestic Engineering, 164:2:85, (August 1944)

124. Plumbing's Vital Role in Restaurants. Sanitary Engineer, 38:12:30, (December 1944)

125. Latest Polio Plumbing Tie, Domestic Engineering, 167:1:123 (January 1946).

126. Back Siphonage Hazards Open a Beauty Shop Market. Domestic Engineering, 167:4:116 (April 1946).

127. Where to Look for Cross Connections or Back Siphonage: State Board of Examiners of Plumbers of Massachusetts. Yankee Plumber, 8:11:16, (November, 1940).

128. Cross Connection Report. Domestic Engineering, 166:3:103, (September 1945).

129. Perfect Plumbing for Cleveland, Plumbing and Heating Business, 3:6:11, (December 1940).

AMERICAN PUBLIC HEALTH ASSOCIATION:

130. An Epidemic of 3,000 Cases of Bacilliary Dysentery Involving a War Industry and Members of the Armed Forces, September, 1944.

131. Essential Features in the Design of Sanitary Drinking Fountains. American Journal of Public Health, 19:1223 (November 1929).

132. Eliminating Health Hazards in Plumbing. American Public Health Association Year Book, p. 129 (1930-1931).

133. Plumbing: Report of the Joint Committee of the Conference of State Sanitary Engineers and the Public Health Engineering Section, 29:2:92, (February 1939).

134. Manufacturers Giving More Attention to Public Health Aspects of Plumbing Fixture Design. American Public Health Association Year Book, p. 80 (1933-1934).

135. Recent Developments in Plumbing as Related to Public Health. American Public Health Association Year Book, p. 226 (1935-1936).

136. Newer Aspects of Amebic Dysentery. American Journal of Public Health, 26:1023 (October, 1936).

137. Plumbing. American Public Health Association Year Book, p. 159, (1936-1937).

138. Basic Principles of Healthful Housing. American Journal of Public Health, 28:351 (March 1938).

AMERICAN SOCIETY OF SANITARY ENGINEERING:

139. Cross Connections. Proceedings, American Society of Sanitary Engineering, 14:75 and 158 (1928-1929); 15:239 (1930-1931).

140. Report of Conference on Cross Connections, Washington, D. C. (February 24-25, 1932).

AMERICAN STANDARDS ASSOCIATION:

141. Air Gaps and Back Flow Preventers in Plumbing Systems, American Standards, A 40.4 and A 40.6, 6:14, (June 1943).

AMERICAN STERILIZER COMPANY:

142. Relating to the Selection, Arrangement and Installation of Sterilizers. Sanitary Protection of Sterilizer Connections. American Sterilizer Company Catalog, Section Z, p. 15, (January 1936).

AMERICAN WATER WORKS ASSOCIATION:

143. Final Report of the Committee on Sanitary Drinking Fountains of the American Water Works Association. Journal, American Water Works Association, 7:33, (1920).

144. Report of Committee No. 8 on Cross Connections. Journal, American Water Works Association, 25:296, (March, 1933).

145. Report of Committee on Convention Hotel Sanitation, Journal, American Water Works Association, 28:251, (February, 1936).

146. Report on Cross Connections and Back Siphonage Connections Under War Conditions, 37:427, (May, 1945).

ELLEN, E. JERRY:

147. A Cross Connection Survey. Journal, American Water Works Association, 40:6:641, (June 1948).

ALIQUIST, FREDERICK O. A.:

148. Double Check Valve Performance, Water Works and Sewerage, 90:329, (September 1943).

149. Cross Connections. Water Works Engineering, 100:703 & 721, (June 25, 1947).

ANGUS, W. M. and FRANCIS, CARL:

150. Leaky Cross Connections Located by Alkali Test. Engineering News-Record, 84:25:1187, (June 17, 1920).

ARNOLD, G. E.:

151. Back Siphoning and Cross Connections. Journal, American Water Works Association, 28:234, (February 1936).

152. Cross Connection in Sewage Plants. Sewage Works Journal, 14:608, (May, 1942).

BALTIMORE, CITY DEPARTMENT OF HEALTH:

153. Plumbing Cross Connection Result in Acute Lead Poisoning, Baltimore Health News, 13:8:52 (August, 1936).

BARLOW, F. L.:

154. Some Notes on American Plumbing. Journal, Royal Sanitary Institute, 67:12 (January 1948).

BARSANTEE, HARRY:

155. That Chicago Epidemic. The Quill, 22:4 (April 1934).

BARTON, D. G.:

156. Back Siphonage. The Yankee Plumber, 7:11:6 (November 1939).

BAXTER, A. C.:

157. The Role of the Plumber in his Local Health Program. Illinois Master Plumber, 23:17 (April 1938).

BEAM, JAMES R.:

158. Some Suggestions on Testing Water Closet Bowls. Proceedings, American Society of Sanitary Engineering, p. 168 (1933).

BENNETT, ALBERT A.:

159. Research Work as Applied to Scientific Development and as Employed for Sanitary Regulations. Western Plumbing and Heating Journal, p. 5 (December 1933).

BERGMAN, LEONARD A.:

160. A Check on Cross Connections. Water Works Engineering, 94:1137 &1182, (September 10, 1941).

BERRY, A. E.:

161. Plumbing Legislation, Canadian Journal of Public Health, 28:34:282 (June 1943).

BEVIER, B. V.:

162. An Outbreak of Typhoid Fever Caused by Cross Connection with Plumbing Fixtures. Ohio Conference on Water Purification. Annual Report, 18:102 (1938).

163. Procedure for the Survey and Elimination of Cross Connections, Twentieth Annual Report of Ohio Conference on Water Purification, p.87, (October 1940).

BOARDEN, W. W.:

164. Acute Infectious Gastroenteritis. American Journal of the Medical Sciences, 196:835 (December 1938).

BOOSEY, NORMAN:

165. Plumbing Hazards to Health. The Ladle, 15:16 (March 1939).

BROOKS, PAUL B.:

166. The Plumbing Doctor. Plumbing and Heating Business, 3:2:25, (September 1940).

BROOKS, R. A.:

167. Cross Connections. Proceedings, American Society of Sanitary Engineering, p. 47 (1933).

BROWN, GLENN:

168. Reports on Experiments in Trap Siphonage. Museum of Hygiene, U. S. Navy Department, Washington, D. C. (1886).

BUNDESEN, H. N.:

169. Amebic Dysentery - Its Influence on Plumbing. Illinois Master Plumber, 19:7, (March 1934).

170. Amebic Dysentery in Chicago. American Journal of Digestive Diseases and Nutrititon, 1:1:9 (March 1934).

171. Prevention of Amebic Dysentery. National Association of Master Plumbers, Bulletin, 2:10:17 (September 1934) and 2:11:13 (October 1934).

172. The Chicago Epidemic of Amebic Dysentery. Public Health Reports, 49:1266, (October 26, 1934).

173. Why Cross Connections are Health Hazards. Domestic Engineering, 145:52 (February 1935).

174. Health Hazards in Plumbing. Modern Hospital, 44:71 (April 1935).

175. Revival of Interest in Safety of Plumbing Sweeps over Country. National Association of Master Plumbers, Bulletin, 3:4:12, (April 1935).

176. Dr. Bundesen Urges Safe Plumbing Installations. National Association of Master Plumbers, Bulletin, 3:5:4 (May 1935).

177. Plumbing in Relation to Infectious Diseases. American Journal of Tropical Medicine, 15:4:455 (July 4, 1935).

178. What of the Future in Plumbing? Illinois Master Plumber, 21:2 (February 1936).

BUNDESEN, H. N., TOMMEY, F. O., and RAWLINGS, I. D.:

179. The Outbreak of Amebiasis in Chicago, American Medical Association Journal, 102:5:367 (February 3, 1934).

BURGRESS, PHILIP:

180. Legal Aspects of Damages Occurring from Leaks. Journal, American Water Works Association, 31:955 (June 1939).

BURKE, ORMOND J.:

181. How New York City Tests Vacuum Breakers. Water Works Engineering, 94:1133 & 1179 (September 10, 1941).

CALMAN, JOHN J.:

182. The Activities of the National Association of Master Plumbers in Connection with Amebic Dysentery. National Association of Master Plumbers, Bulletin, 3:5:8 (May 1935).

CAMP, THOMAS R.:

183. The Hydraulics of Water Closet Bowls and Flushing Devices (Cooperative Research Project of the Massachusetts State Association of Master Plumbers and the Department of Civil and Sanitary Engineering of the Massachusetts Institute of Technology), Pamphlet, 126 pp. (May 1936).

CANTON, E. J.:

184. Cross Connections and their Elimination. Proceedings, 2nd Annual Conference, Maryland Water and Sewerage Assocation, p. 88 (1928).

CARPENTER, LEWIS V.:

185. Plumbing Defects: Their Significance. The Greater City Plumber, 3:1:14, (January 1937).

CARY, WILLIAM H. and BELL, A. P.:

186. Flushometer Valve Problems in Temporary Shut Offs. Journal, American Water Works Association, 40:5:504, (May 1948).

CHASE, E. SHERMAN:

187. Present Status of Cross Connection Control, Journal, American Water Works Association, 32:1737, (October 1940).

CHICAGO, CITY DEPARTMENT OF HEALTH:

188. Cross Connections with the Water Supply System. Report of 1923-1925, p. 468.

189. Drinking Fountains, Report of 1926-1930, p. 375.

190. Plumbing Cross Connections. Report of 1926-1930, p. 376.

CLAFFEY, THOMAS J.:

191. Tests on Water Closets and Flush Valves. Proceedings, American Society of Sanitary Engineering, 14:71 (1928-1929).

192. Research Upon Siphonage Through Flush Valves. Proceedings, American Society of Sanitary Engineering, 15:271 (1930-1931).

193. Report of Research Committee on Sanitary Drinking Fountains, Proceedings, American Society of Sanitary Engineering, 16:203 (1932).

194. Report of Research Committee on Cross Connections Through Flush Valves. Proceedings, American Society of Sanitary Engineering, 16:206 (1932).

195. Report of Special Committee No. 5 on Plumbing Fixtures. Proceedings, American Society of Sanitary Engineering, 17:770 (1933-1935).

CLEVERDON, W. S. L.:

196. New Plumbing Data Revealed in "Lab" Tests. Plumbing and Heating Contractors Trade Journal, 93:2:35 (May 1932).

197. Co-functions of Traps and Vents in Plumbing. Plumbing and Heating Trade Journal, 96:2:28 (February 1934) and 96:3:31 (March 1934).

198. Why Good Plumbing and Health Go Together. Domestic Engineering, 143:4:38 (April 1934).

COLEMAN, C. J.:

199. Adoption of Sanitary Engineering Principles in Hospital Fixtures and Equipment. Proceedings, American Society of Sanitary Engineering, 16:153 (1932).

COLLINS, W. E.:

200. The Cross Connection Problem, Proceedings, 20th Annual Texas Water Works Short School. (February 1938).

COLORADO, STATE BOARD OF HEALTH:

201. Plumbing Laws - Rules and Regulations Pertaining. Pamphlet, 59 pp. (1937).

CONNECTICUT, STATE DEPARTMENT OF HEALTH:

202. Waterbury Acts to Prevent Pollution of House Water Piping. Connecticut Health Bulletin, 44:38 (February 1930).

203. Requirements for Drainage and Toilet Systems. Connecticut Health Bulletin, 52:1:14 (January 1938).

CONNOLLY, JOEL I.:

204. Modern Plumbing: The Price of Public Health. Domestic Engineering, 121:10:18 (December 3, 1927).

205. Cross Connections. Domestic Engineering, 123:12:18 (June 23, 1928).

206. Submerged Inlet Fixtures. Plumbers and Contractors Trade Journal, 85:1;70 (July 1, 1928).

207. Now We Will Do Some Plumbing. Domestic Engineering, 124:10:28, (September 8, 1928).

208. Progress in Elimination of Cross Connections with Especial Reference to Hospitals. Proceedings, American Society of Sanitary Engineering, 12:234 (1928-1929).

209. Cross Connections. Proceedings, American Society of Sanitary Engineering, 14:102 (1928-1929).

210. Sanitary Aspects of Drinking Fountains. Proceedings, American Society of Sanitary Engineering, 15:278 (1930-1931).

211. The Function of the City Sanitary Engineer. Municipal Sanitation, 1:22 (January 1930).

212. Faulty Private Cross Connections Prove Perpetual Menace to Health. Water WorksEngineering, 83:1081 (July 16, 1930).

213. Private Cross Connections and Similar Menaces to the Quality of Water. Water Works and Sewerage, 77:309 (September 1930).

214. Danger of Private Cross Connections. Canadian Engineer, 59:20:627, (November 11, 1930).

215. Private Cross Connections. Proceedings, 13th Annual Texas Water Works Short School, p. 33 (1931).

216. Private Cross Connections and Similar Menaces to Public Water Supply Quality. Journal, American Water Works Association, 23:495 (April 1931).

217. The Importance of Plumbing to Public Health. Proceedings, American Society of Sanitary Engineering, p. 176 (1933).

218. Plumbing and Health in Chicago. Illinois Master Plumber, 18:17 (June, 1933).

219. Safeguarding the Sterile Water Supply. Modern Hospital, 45:1:61 (July 1935).

220. Serving Disease to Consumers Via Pipes and Fixtures. Water Works Engineering, 89:631 (May 27, 1936).

221. Regulation of Plumbing as a Public Health Measure. Transactions, Southern Branch of the American Public Health Association, p. 63. (1937).

222. Plumbing as an Industrial Hygiene Problem. Illinois Master Plumber, 23:13 (July 1938).

223. Cross Connection Crimes. Engineering News-Record, 120:16:575, (April 21, 1938).

224. Good Plumbing Plus Vigilance Equals Health. The Ladle, 14:9 (August 1938).

225. Plumbing in Low Cost Housing. American Journal of Public Health, 28:954 (August 1938).

226. Plumbing as an Industrial Hygiene Problem. Industrial Medicine. 7:555, (September 1938).

227. The Part of Plumbing in Preserving Water Purity. Amour Engineer and Alumnus, 6:11 & 45, (October 1940).

COOK, HORACE J.:

228. Progress Report of the Committee on Cross Connections in House Plumbing. Journal of the Maine Water Utilities Association, 17:11 (March 1941).

CORNELIUS, LOUIS A.:

229. They Die From Neglect. Pamphlet, 56 pp. (1936).

COSWELL, H. H.:

230. City Ordinances Against Cross Connections. Journal, American Water Works Association, 38:460, (April 1946).

231. Cross Connection and Plumbing Hazard Elimination in Ann Arbor. Public Works, 77:24, (August 1946).

COUSIVEAU, AIME:

232. The Necessity of Provincial Plumbing Codes. Canadian Public Health Journal, 32:472 (September 1941).

COWLES, M. W.:

233. Progress in Plumbing Standardization. Journal, American Water Works Association, 33:1565 (September 1941).

234. Customers' Complaints as a Guide to Better Service, Journal, American Water Works Association, 37:1042 (October 1945).

235. What Interest Has a Water Purveyor in Interior Plumbing Systems in Relation to Cross Connections? Journal, New England Water Works Association, 51:261 (September 1937)

236. When is Plumbing a Health Hazard? The Ladle, 14:13 (June, 1938).

237. Disapproved Plumbing: How Dangerous is it? Plumbing and Heating Journal, 104:6:24 (June 1938).

238. Disapproved Plumbing Fixtures: How Hazardous? Water Works and Sewerage, 85:801, (August 1938).

CRONKRIGHT, ARTHUR B. AND MILLER, ARTHUR P.

239. The Effect of Certain Small Filters on Plate Counts of Water Passing Through Them. Public Health Reports, 53:505, (April 1, 1938).

240. Added Security for the Public. Water Works Engineering, 91:492, (April 13, 1938).

241. Vacuum Frequency: The Measure of Hazard in Cross Connections. Engineering News-Record, 123:3:64, (July 20, 1939).

CROTTY, JOSEPH J.:

242. More Business: Public Health Protection Possible if Contractors And Associations Work to Impress Law-makers with Benefits of Reinspection. Plumbing and Heating Contractors Trade Journal, 92:1:34, (October 15, 1931).

243. Periodical Reinspection of Plumbing: A Factor in Disease Prevention. Plumbing and Heating Trade Journal, 97:4:46 (October 1934).

244. Reinspection of Plumbing Prevents Disease. Domestic Engineering, 144:5:137, (November 1934).

CURRY, D. V.:

245. How to Help Control Polio, Sanitary Engineer, 39:7:18, (July 15, 1945).

CURTIN, FRANK G.:

246. Back Siphonage and Aspiration. The Yankee Plumber, 7:9:6, (September 1939).

CYR, RENE:

247. Cross Connections in Water Supplies. Canadian Public Health Journal, 29:131, (March 1938).

DASHIEL, G. M. and WHEDBEE, EDGAR:

248. Cross Connection Elimination War in Texas Cities. Engineering News-Record, 104:11:444, (March 13, 1930).

DAWSON, F. M.:

249. Report on Tests of Flushometer Valves. The Chicago Hospital Association, Bulletin, p. 3, (September, 1930).

250. New Developments and Trends in Water Treatment. Water Works Engineering, 89:683 (May 27, 1936).

251. Plumbing Free From Pollution. Nation's Schools, 23:74 (May, 1939).

252. Safe Plumbing Began in the Laboratories. The Ladle, 16:1:19 (January 1940).

253. Pollution in the Plumbing. Modern Hospital, 53:6:30, (December 1939).

DAWSON F. M. and KALINSKE, A. A.

254. Vacuum Breaker Development for Back Siphonage Prevention, Journal, American Water Works Association, 29:307 (March 1937).

255. Cross Connections in Air Conditioning Equipment. Journal, American Water Works Association, 29:1673 (November 1937).

256. Control of Water Piping from Main to Consumer. Journal, American Water Works Association, 30:464 (March 1938).

257. Report on Plumbing Cross Connections and Back Siphonage Research. National Association of Master Plumbers, Technical Bulletin No. 1, 79 pp. (1938).

258. Venting of the Plumbing-Drainage System. Plumbing and Heating Business, 1:6:14 (February, 1939).

259. Evaluation of Back Siphonage Prevention Methods. Proceedings, Minnesota Section, American Water Works Association, p. 36, (August 24-26, 1939).

260. The Prevention of Back Siphonage. Plumbing and Heating Business, 2:2:21 (September 1939).

261. Pollution of Water Due to Faulty Water Piping and Plumbing Fixtures. Official Bulletin, North Dakota Water and Sewage Works Conference, 8:12 (September 1940).

262. New Plumbing Standards to Keep Drinking Water Pure. Industrial Standardization, 14:235 (August 1943).

263. Interior Water Supply Piping. Plumbing and Heating Business, 3:4:21, (November, 1940); 3:5:16 (December 1940); 3:6:22 (January 1941); 3:7:21 (February 1941).

264. New Types of Back Flow Preventers. Plumbing and Heating Business, 6:7:21 (February 1941).

265. Water Supply Piping for the Plumbing System. Technical Bulletin No. 3, National Association of Master Plumbers, 1942.

266. Vacuum Breaker Development for Back Siphonage Prevention. New Series No. 338, University of Iowa Studies (Studies in Engineering), Reprint No. 2, July 15, 1937; and Journal, American Water Works Association, 29:3:307, (March, 1937).

267. Safety Devices on Domestic Hot Water Supply Systems. Plumbing and Heating Business, 2:8:21 (March 1940).

268. Water Works School; Cross Connections. Water Works Engineering, 97:11:572, (May 31, 1944).

DAWSON, F. M., KING, F. R. and KALINSKE, A. A.:

269. How to Build a Cross Connection and Back Siphonage Exhibit. Domestic Engineering, 147:56 (February 1936).

DAY, LOUIS J. and STEDMAN, C. W.:

270. Water Supply Connection: A Treatise on Swimming Pool Design. Josam Manufacturing Company, Cleveland, Ohio, A. I. A. File No. 35-f-2, 33 pp.

DEMPSTER, ANDREW T.:

271. Detroit's Plumbing 70 Per Cent Siphonable. The Ladle, 13:13 (July, 1937).

272. Cross Connections and Back Siphonage. Journal, American Water Works Association, 38:465 (April 1946).

DERBY, RAY L.:

273. Cross Connections Between Water and Sewage Systems. Journal, California Sewage Works Association, 5:1:127 (1932-1933).

DICK, ROBERT:

274. An Analysis of 800 Plumbing Codes, Plumbing and Heating Business, 3:3:16, (October 1940).

DIETER, LOUIS V.:

275. The Relative Sanitary Value of Different Types of Drinking Fountains. Part I: The Results of Tests of Vertical Nozzel Types: Part II: How the Fountains are Used and the Reults of Tests of Sloping Stream Types. American City, 21:452 and 549 (November and December, 1919).

DOUGLAS, A. M.:

276. Plumbing Installations that Safeguard Health. Proceedings, 11th Annual Conference, Texas Public Health Association, p. 112, (1933).

DUGGER, E. F.:

277. Should Plumbing Installations be Approved by the Water Department? Journal, American Water Works Association, 30:1775, (November, 1938).

DUNLAP, J. H.:

278. The Sanitary Drinking Fountain. Journal, American Water Works Association, 4:65, (March 1917).

279. Common Sense, Science and Drinking Fountains. American City, 20:470, (May 1919).

ECKART, N. A.:

280. Ending Cross Connections in San Francisco; California Hotels to Protect World's Fair Visitors. Water Works Engineering, 92:1103, (August 30, 1939).

EHLERS, V. M. and STELL, E. B.:

281. Cross Connections in Plumbing. Municipal and Rural Sanitation, McGraw-Hill, New York, N. Y., p. 280 (1937).

EHLERS, V. M. and TURNER, O.:

282. Cross Connections. Proceedings, 18th Annual Texas Water Works Short School, p. 85, (1936).

ELLIS, J. W.:

283. The Cross Connection Problem. 15th Annual Report of the Ohio Conference on Water Purification, Cleveland, Ohio, p. 36, (October 1935).

284. Cross Connection Problem in Water Supplies. Canadian Engineer, 71:23:17 (December 8, 1936).

EL PASO, TEXAS:

285. Cross Connection Items. El Paso, Texas Plumbing Ordinances, Section 22; 25 (c), (d), (i) and (n); and 26 (a) to (p).

FAIR, G. M.:

286. The Flush Valve. Journal, New England Water Works Association, 35:137 (June 1921).

FEILITZCH, BAURAT V.:

287. "Über eine neue druckspülerausführung. (Notes on a new flush valve), Das Gas und Wasserfach, 75:218 (March 19, 1932).

FERGUSON, G. H.:

288. Cross Connection Dangers in Plumbing. Canadian Public Health Journal, 24;580 (December 1933).

FERGUSON, WARREN T.:

289. Vacuum Limitation, Plumbing and Heating Journal, 110-111:1:24, (January 1941).

FISH, C. T.:

290. Plumbing for the Plant. National Safety News, 40:3:18 (September 1939).

FISHER, L. M.:

291. Cross Connections. Proceedings, 9th Annual Meeting, Florida Section, American Water Works Association (March 1935).

FLETCHER, A. H.:

292. Quasi-public Water Supplies and Cross Connections with Municipal Water Supplies. Journal, American Water Works Association, 29:78, (January 1937).

293. Administrative Problems of Preventing and Correcting Defective Plumbing. Journal, American Water Works Association, 31:969, (June 1939).

FOLEY, A. R., FAILE, J. L. and BRANDON, K. F.:

294. Hospital Plumbing Epidemic of Paratyphoid A., Canadian Public Health Journal, 27:313, (July 1936).

FRENCH, T. R.:

295. This Thing Called Vacuum. Domestic Engineering, 130:4:57, (February 22, 1930).

FROMMELT, HORACE A.:

296. Is the School House Plumbing Safe? American School Board Journal, 90:21, (May, 1935).

GARRETT, R. W.:

297. Sanitary Regulations Disregarded in Housing Program. Water and Sewage, 83:82, (November 1945).

GEIGER, J. C.:

298. Pollution of Drinking Water Through Cross Connection with Fire Lines, Journal, American Water Works Association, 32:2006, (December 1940).

GEIGER, J. C., BECKER, G. H. and GRAY, J. P.:

299. Epidemiology of Amebiasis. American Journal of Public Health, 25: 389, (April 1935).

GEIGER, J. C., CROWLEY, A. B. and ARNOLD, G. E.:

300. San Francisco's Hotels are Examined for Cross Connections. American Journal of Public Health, 29:927, (August 1939).

GEIGER, J. C., CROWLEY, A. B. and HYDE, C. G.:

301. Gastro Enteritis Epidemic in Large Office Group. Journal, American Water Works Association, vol. 33, 1941.

GILBERTSON, W. E.:

302. Cross Connections in North Dakota. Official Bulletin, North Dakota Water and Sewage Works Conference, 8:16, (September 1940).

303. Cross Connections in North Dakota. Plumbing-Drainage Topics, 4:8, (August 1943).

GLEASON, ROBERT J.:

304. The World's Safest Plumbing. Plumbing and Heating Business, 3:2:11, (September, 1940).

305. The Problem of Back Flow Preventive Measures Employed at the New York World's Fair. American Journal of Public Health, 30:1159, (October 1940).

GOGLIA, M. C.:

306. The Relation of Plumbing to Public Health. Philadelphia Department of Public Health, Monthly Bulletin, p. 37, (April 1929).

GOLDEN, C. E. and HUNTER, R. B.:

307. Backflow Prevention in Over-rim Water Supplies. National Bureau of Standards Report BMS 28, 17 pp., (August 1939).

GORMAN, A. E.:

308. Cross Connections in Chicago. Journal, American Water Works Association, 15:587, (June 1926).

309. Potential Health Hazards in Distribution of Water. Journal, American Water Works Association, 31:1143, (July 1939).

GOUDEY, R. F.:

310. Practical Aspects of Cross Connection, Inter Connection and Back Flow Protection. I-Scope of the Cross Connection and Inter Connections. Journal, American Water Works Association, 33:391, (March 1941).

311. Practical Aspects of Cross Connection, Inter Connection and Back Flow Protection. III-Factors Involved in Connection Protection. Journal, American Water Works Association, 33;397, (March 1941).

312. Practical Aspects of Cross Connection, Inter Connection and Back Flow Protection. IV-Summary of Connection Protection and Back Flow Control Procedures Throughout the United States. Journal, American Water Works Association, 33:409, (March 1941).

313. Practical Aspects of Cross Connections. V-Mechanical Protection Devices. VI-Principles and Protection Devices Involved in Connection Protection. Journal, American Water Works Association, 33:441, (March 1941).

314. Practical Aspects of Cross Connection, Inter Connection and Back Flow Protection. VII-Recommendations and Quotations from City Ordinances and Water Department Regulations. Journal, American Water Works Association, 33:454, (March 1941).

315. Cross Connections to Steam Boilers, Water Works And Sewerage, 87:8:305, (August 1940).

GOUDEY, R. F. and BLAKE, H. R.:

316. Dangers of Back Siphonage of Contaminated Air. Municipal Sanitation, 7:437, (December 1936).

GREEN, CARL E.:

317. Why Plumbing Control is a Health Department Function. Plumbing and Heating Business, 4:5:24, (December 1941).

GROENIGER, W. C.:

318. Insurance Against Water-Borne Diseases Through Plumbing Fixtures. Proceedings, American Society of Sanitary Engineering, 13:203, (1926-1927); Plumbing and Heating Trade Journal, 83:506 (September 1, 1927).

319. Pollution of Domestic Water Supplies Through Unusual Cross Connection. American City, 39:96, (September 1928).

320. Cross Connections. Proceedings, American Society of Sanitary Engineering, 15:239 (1930-1931); 14:75 and 158 (1928-1929).

321. The Contamination of Water Supply Through Cross Connections. Plumbers and Heating Contractors Trade Journal, 86:1:18 (January 1, 1929).

322. Problems in Cross Connections. Municipal Sanitation, 1:250, (May 1930).

323. Where the Siphon and Siphonage Make Sanitary Plumbing Fixtures Insanitary and How Cross Connections Can be Avoided and Corrected. Proceedings, American Society of Sanitary Engineering, 15:75 (1930-1931).

324. Check Valves as Siphon Preventors. Proceedings, American Society of Sanitary Engineering, 15:90, (1930-1931).

325. Report of Research Committee of American Society of Sanitary Engineering. Pamphlet, 21 pp. (September 9, 1931).

326. A Menance to the Public Health that means More Work for Contractors. Plumbing and Heating Contractors Trade Journal, 92:9:19, (November 1, 1931).

327. History and Performance of Water Closet Bowls. Proceedings, American Society of Sanitary Engineering, 16:115, (1932).

328. A Discussion of Facts Relating to the Problem of Cross Connections Cause by Under Rim Inlet Water Supplied Plumbing Fixtures. Proceedings, American Society of Sanitary Engineering, 17:25 (1933-1935).

329. Elimination and Prevention of Health Hazards Caused by Cross Connections. Proceedings, American Society of Sanitary Engineering, 17: 367, (1933-1935).

330. Plumbing in Hotels. Proceedings, American Society of Sanitary Engineering, 17:654, (1933-1935).

331. Typhoid Fever Outbreak on Manhattan Street, Middletown, Ohio, and its Cause. Pamphlet, 15 pp. (1938).

332. The Battle Against Water System Backflows. Plumbing and Heating Business, 113:11:20. (November 1942).

333. Water You Can Drink from Any Faucet, Part I. Plumbing and Heating Journal, 115:3, (March, 1944).

334. Water You Can Drink From Any Fountain, Part II. Plumbing and Heating Journal, 115:6, (April 1944).

HALPIN, H. E.:

335. Tanks for Water Service in High Buildings. Journal, New England Water Works Association, 51:273, (September 1937).

HANSEN, PAUL:

336. Unsuspected Unusual and Little Known Factors in Water Supply Quality. Journal, American Water Works Association, 24:1780, (November 1932).

HARDY, A. V. and SPECTOR, B. K.:

337. The Occurrence of Infestations with E. Histolytica Associated with Water-Borne Epidemic Diseases. Public Health Reports, 50:323, (March 8, 1935).

HARRINGTON, A. V.:

338. Special Equipment Cross Connections. Journal, New England Water Works Association, 51:270, (September 1937).

HATCHER, M. P.:

339. Essential Factors in Design of Swimming Pools. Municipal Sanitation, 2:347, (July 1931).

HAYES, HARRY:

340. Elimination of Cross Connections in Los Angeles, California, Proceedings, American Society of Civil Engineering, 72:400, (March, 1946).

341. Elimination of Cross Connections in Los Angeles, California: With Discussions, Transactions of the American Society of Civil Engineers, 111:2279:613. (1946).

HEALTH, R. F.:

342. Swimming Pool Construction: Safeguarding Against Disease. The Surveyor (London), 96:2484:232, (September 1, 1939).

HENDERSON, C. J.:

343. Pollution of Domestic Water Supply. Proceedings, American Society of Sanitary Engineering, 13:47 and 224, (1926-1927).

HIRMAN, JACK J.:

344. Menance to Consumers Through Faulty Plumbing. Water Works Engineering, 88:1355, (November 27, 1935).

HOFFERT, J. R.:

345. Cross Connections Between Potable Water Supply Systems and Sewerage Systems, Sewage Works Journal, 14:604, (May 1942).

HOLMQUIST, C. A. and DEVENDORF, EARL:

346. Safeguarding and Eliminating Cross Connections in New York State. Journal, American Water Works Assoication, 22:103, (January 1930).

HOUSTON, TEXAS:

347. Water Supply Cross Connections. Houston, Texas Plumbing Ordinance, Section 9, Paragraph (q), (1931).

HOWARD, CHARLES D.:

348. New Plumbing Code Adopted. New Hampshire Health News, 16:4, (April 1938).

HUNTER, R. B., GOLDEN, G. E. and EATON, H. N.:

349. Cross Connections in Plumbing Systems. Journal of Research, National Bureau of Standards, 20, 479, (April 1938).

INDIANA, STATE BOARD OF HEALTH OF:

350. Swimming Pool Regulations. Monthly Bulletin, 33:209, (January 1930).

351. Cross Connections in Gas Refrigerators. Monthly Bulletin, 33:61, (April 1930).

INGHAM, EDWARD:

352. Safety Valves for Hot Heating Boilers, International Engineer, 82:189, (December 1942).

JAMESON, W. E.:

353. Control of Plumbing and Raising of Plumbing Standards. Texas Water Works Short School, 22:29, (1940).

JAMES, GEORGE N.:

354. It's Not Good Plumbing. Sanitary Engineering, 38:6:17, (June 15, 1944)

JOHNSON, W. SCOTT:

355. A Survey of Potential Health Hazards Due to Faulty Plumbing. Journal, American Water Works Association, 28:214, (February 1936).

356. Plumbing Hazard Survey of Pasteurization Plants. American Journal of Public Health, 26:229, (March, 1936).

357. Plumbing the Situation. Modern Hospital, 47:4:94, (October 1936).

KALINSKE, A. A.:

358. Cross Connections in Plumbing and Water Supply Systems. The Contamination of Water Supplies and Methods of Corrections and Eliminations of Cross Connections from the Plumbing System. Wisconsin State Board Health. Journal of the American Water Works Association, 35:951, (July 1943).

KALINSKE, A. A. DAWSON, F. M. and KING, F. R.:

359. Cross Connections in Plumbing and Water Supply Systems. Bulletin, Wisonsin State Board of Health and the University of Wisconsin, 76 pp. (1936).

KALINSKE, A. A. and McLEOD, A. M.:

360. All "Anti-Siphon" Traps Siphon if Unvented. Plumbing and Heating Business, 1:4:27, (December 1938).

KEEFER, C. E.:

361. Cross Connection Hazards of Sewage Disposal Plants, Engineering News-Record, p. 237, (August 13, 1936).

KEGEL, ARNOLD H.:

362. Contamination of Water In Hospitals as a Cause of Post-Operative Infections. Transactions, American Hospital Association, 30:575 (1928).

363. The Relationship of Hospitals to the Health Department of Large Cities. Transactions, American Hospital Association, 31:33, (1929)

364. Faulty Plumbing as a Source of Infection. Plumbers and Heating Contractors Trade Journal, 86:246 (February 1, 1929).

KELTING, OTTO:

365. Versuche mit abortspülhähnen und bemessung der fausleitungen. (Research with Flush Valves and Measurements of Discharge in Domestic Plumbing Systems.) Das Gas-und Wasserfach, 75:7, (January 2, 1932).

KESSLER, LEWIS H.:

366. Hydraulics in Small House Plumbing. Proceedings, American Society of Sanitary Engineering, 17:215, (1933-1935).

KING, F. R.:

367. Report of Bureau of Plumbing and Sanitary Engineering. Wisconsin State Board of Health, p. 151. (1933).

368. Health Protection for the Patrons of the Modern Tavern. Domestic Engineering, 142:3:132, (September, 1933).

369. Elimination of Cross Connections. Domestic Engineering, 151:5:46, (May 1938).

KOLLISH, F. J..

370. President Vetoes Congress Demand for U. S. Survey as Faulty Plumbing in National Capitol is Revealed. Plumbing and Heating Trade Journal, 98:6:25, (June 1935).

LAWRENCE, R. E.:

371. A Study of Defects in Hospital Sterilization Practice. Journal, Kansas Medical Society, 33:200, (June 1932).

372. Cross Connection Elimination in Nashville. Journal, American Water Works Association, 31:6:977, (June 1939).

LINK, E.:

373. Spulhahnen mit rohrunterbrecher fur aoortspulleitungen. (Flush Valves with Siphon Breakers for Toilet Flushing Installations). Das Gas-und Wasserfach, 72:489, (May 25, 1929).

LOUIS, LEO:

374. Water-Borne Outbreak of Gastro Enteritis in an Industry. Indiana State Board of Health Bulletin, 49:35, (February 1946); Journal, American Water Works Association, 38:1316, (November 1946).

LOWE, ROBERT P.:

375. Elimination of Cross Connections in Los Angeles, California, Proceedings, American Society of Civil Engineering, 71:1305, (October 1945).

McAFEE, H. D.:

376. Correction of Faulty Plumbing. Journal, American Water Works Association, 28:935, (July 1936).

McCOY, G. W. and CHESLEY, A. J.:

377. Control of Amebic Dysentery. Journal, American Medical Assocation, 103:15:1145, (October 13, 1934).

McDONALD, R. ST. J.:

378. Plumbing-Borne Diseases. Canadian Public Health Journal, 30:198, (April, 1939).

379. Plumbing-Borne Diseases, Monthly Bulletin, Indiana State Board of Health, 43:2:28, (February 1940).

McGONEGAL, A. R.:

380. Plumbing and Sanitation of Industrial Buildings. The Architectural Forum, 51:425, (September 1929).

381. Menace of Cross Connections Seen in Faulty Wastes of Refrigerators. Plumbing and Heating Contractors Trade Journal, 93:5:55. (Aug. 1932).

382. Beer Equipment Installations and the Menace of Cross Connections. Plumbing and Heating Contractors Trade Journal, 94:5:50, (May 1933)

383. "Amebiasis" - Black Eye or Bull's Eye for the Plumbing Trade? Plumbing and Heating Trade Journal, 96:3:17, (March 1934).

384. Use of Water for Air Conditioning and Refrigeration. Proceedings, 9th Annual Conference, Maryland-Delaware Water and Sewage Association, p. 106, (1935).

385. Look Out for Cross Connections in Air Conditioning! Plumbing and Heating Trade Journal, 102:5:40, (May 1937).

386. Discussion on Plumbing Hazards. Journal, American Water Works Association, 31:987, (June 1939).

387. Industrial Piping-Its Renovation, a Health Necessity. Plumbing and Heating Business, 2:9:24, (April 1940).

388. Privileged Pollution. Plumbing and Heating Business, 2:11:27, (June 1940).

389. Whose Problem is Hazardous Plumbing? Plumbing and Heating Business, 3:4:24, (November 1940); 3:5:25, (December 1940); 3:6:24, (January 1941).

MAGATH, THOMAS B.

390. The Water Transmission of Infections with Special Reference to Amebiasis. Journal, American Water Works Association, 27:63, (January 1935).

MAIER, F. J.:

391. Using the Bibliography on Plumbing and Public Health. Plumbing and Heating Business, 3:3:16, (October 1940).

MANOSA, M.:

392. The Problem of Cross Connection: An Appeal to the Medical Profession. Journal, Phillippine Island Medical Association, 16:235, (April 1936).

MARSTON, GRANKE A.:

393. Legal Decisions Relating to Distribution of Public Water Supplies. Journal, American Water Works Association, 32:7:1081, (July 1940).

MARTIN, P. J., JR.:

394. Cross Connections Discovered by Water System Survey at Tucson. Water Works Engineering, 87:20:1124, (October 3, 1934).

MASSACHUSETTS, COMMONWEALTH OF:

395. Cross Connections. Report of the Special Commission to Study and Investigate Public Health Laws and Policies. House No. 1200, p. 110, (December 1936).

MATTHIESON, H. H.:

396. Outlawing Cross Connections. Proceedings, American Society of Sanitary Engineering, 17:891, (1933-1935).

MENDELSOHN, I. W., SCHWARTZ, LOUIS, and FERGUSON, G. H.:

397. Water-Borne Disease Epidemics on Ships. Journal, American Water Works Association, 21:1660, (December 1929).

MINGELINGHAUSEN, M.:

398. Grundlagen für die Berechnung von Hauswasserleitungen. (Rules for the design of domestic plumbing systems). Das Gas-und Wasserfach, 75:865, (October 29, 1932).

MILLER, ARTHUR P.:

399. Plumbing Hazards and Their Evaluation. Journal, American Water Works Association, 30:1702, (October 1938).

400. Cross Connections and Backflow. Master Plumber and Heating Contractor, 10:7:22, (July 1940); 10:8:20, (August 1940); 10:9:20, (September 1940).

MILLER, ARTHUR P. and CHAMBERLAIN, ARTHUR B.:

401. The Public Health Significance of Modern Plumbing. Plumbing and Heating Business, 1:4:14, (December 1938).

402. Inter Connections in Plumbing. Plumbing and Heating Business, 1:5:25 and 1:6:27, (January and February 1939).

403. Wide Research Proved Need for Better Plumbing Fixtures. Plumbing and Heating Business, 1:7:25 and 1:8:26, (March and April 1939).

404. Administrative Actions Directed at Removing Plumbing Inter Connections. Plumbing and Heating Business, 1:9:23 and 1:10:21, (May and June, 1939).

405. Some Factors Influencing the Purity of Water at Plumbing Fixtures. Plumbing and Heating Business, 2:1:23, (August 1939).

406. Rating Plumbing Hazards. Plumbing and Heating Business, 2:2:19, (September 1939).

MINNESOTA, STATE BOARD OF HEALTH OF:

407. Report of Investigations of the Typhoid Fever Epidemic, Minneapolis, Part II: Plumbing Surveys., p. 56, (1935).

408. Plumbing in Relation to Public Health. Bulletin, (1938).

MOORE, ROBERT E.:

409. Legal Aspects of Cross Connection, Inter Connection and Back Flow Protection. I-Introduction, II-Legal Theories and Public Policy Regarding Protection of Public Health, III-Statutory and Common Law Liabilities of Municipalities and Water Companies Generally. Journal, American Water Works Association, 33:495, (March, 1941).

410. Legal Aspects of Cross Connections, Inter Connection and Back Flow Protection, IV-Decisions Regarding Promulgation and Administration of Health Laws, Rules and Regulations. Journal, American Water Works Association, 33:528, (March 1941).

411. Legal Aspects of Cross Connection, Inter Connection and Back Flow Protection, VI-Rules and Regulations of Los Angeles Departments. VII-Proposed Ordinance Regarding Cross Connection, Inter Connection and Back Flow Protection and Appendix, Journal, American Water Works Association, 33:526, (March 1941).

MORRIS, L. B.:

412. Main Pollution by Water Which Has Passed Services. Water Works Engineering, 82:1639, (November 20, 1929).

413. Contamination of Water Systems by Consumers' Water Uses. Journal, American Water Works Assoication, 22:180, (February 1930).

414. Cross Connections with Reference to Plumbing Fixtures and Devices. Water Works Engineering, 85:1437, (November 30, 1932).

415. Cross Connections with Public Water Supplies. Journal, American Water Works Association, 24:1750, (November 1932).

MOURY, C. W.:

416. Status of Cross Connection Regulations. Journal, New England Water Works Association, 49:66, (March 1935).

MURDOCH, W. A.:

417. 102,492 Water Supply Danger Points Found in 980 Hotels. Plumbing and Heating Trade Journal, 98:3:40, (March 1935).

MURPHY, F. M.:

418. Plumbing and Its Relation to Health. Proceedings, 17th Annual Texas Water Works Short School, p. 60, (1935).

MURPHY, J. L.:

419. Another Epidemic From Faulty Plumbing. Plumbing and Heating Business, 9:4:73, (November 1946).

MURRAY, JAMES P.:

420. Protect the Public Health the Photographic Way, Part I. Plumbing and Heating Journal, 115:12, (December 1944).

421. Protect the Public Health the Photographic Way, Part II, Plumbing and Heating Journal, 116:1:40, (January 1945).

NATIONAL INSTITUTE OF HEALTH:

422. Epidemic Amebic Dysentery. National Institute of Health, Bulletin No. 166, (1936).

NEW BEDFORD, MASSACHUSETTS:

423. Regulations Governing Water Service Supply Piping and Fixtures. New Bedford, Massachusetts Water Department, (June 1, 1935).

NEW ENGLAND WATER WORKS ASSOCIATION:

424. The Advisability of Water Departments Regulating Water Piping and Fixtures within Buildings. Journal, New England Water Works Association, 51:259 and 51:476, (September and December, 1937).

425. Cross Connections and Back Siphonage Connections Under War Conditions. Journal, New England Water Works Association, 59:42, (March 1945).

NEW, FRANK:

426. Sanitary Drinking Facilities. Oklahoma Bulletin of Health, 2:115, (September 1944).

NEW YORK STATE DEPARTMENT OF HEALTH:

427. Unusual Sources of Water Pollution. Health News, New York State Department of Health, 7:7:27, (February 17, 1930).

428. Health Hazards of Cross Connections in Buildings. Health News, 10:48:189, (November 27, 1933).

429. Elimination of Health Hazards Caused by Faulty Plumbing Installations and Fixtures. Bulletin No. 28, (1934).

430. Faulty Plumbing Installations: A Public Health Problem. Health News, 13:21:82, (May 25, 1936).

431. Pollution of Build Water Supplies Through Back Siphonage of Sewage, Health News, New York State Department of Health, p. 20, (March 1, 1943).

432. Gastroenteritis in Chautauqua County, Health News, New York State Department of Health, 17:50:204, (December 9, 1940).

OHIO, STATE DEPARTMENT OF HEALTH OF:

433. Plumbing and Drainage; Location, Construction, Installation and Inspection of. Building Code, Part 4, 175 pp. (1936).

OLD, H. N.:

434. Houston Adopts a Cross Connection Idea Worthy of Note. American Journal of Public Health, 24:586, (June 1934).

435. Some Aspects of Interstate Carrier Water Supply Certification. Proceedings, 7th Annual Meeting, Southeast Section, American Water Works Association 5:1:20 (1935)

OLESEN, ROBERT AND ROSENBLUTH, JACOB:

436. A Note on the Incidence of Amebic Dysentery in New York City. Public Health Reports, 50:2:37 (January 11, 1935).

O'NEILL, J. H. :

437. Dangerous Plumbing. Louisiana State Board of Health, Quarterly Bulletin, 26:4 (June 1935).

OTT, O. ..:

438. Back-Siphonage. Western Plumbing and Heating Journal, p. 3, (November 1933).

439. Laboratory Tests Disclose Hazards of Back-Siphonage. Plumbing and Heating Trade Journal, 97:1:30, (July 1934).

OTT, O. W AND MATTHIESON, H. H.:

440. Why Back-Siphonage? Proceedings, American Society of Sanitary Engineering, 17:57, (1933-1935).

PERAZZO, R. J.:

441. Sanitary Installations for Households. Bulletin Obras Sanitarias Nacion (Bulletin of National Sanitary Works), Buenos Aires, 2:357, (October 1938).

PERKINS, FRED A.:

442. Cross Connections. Kentucky Bulletin of the Department of Health, 12:171, (May 1940).

443. Why a Plumbing Code? Plumbing and Heating Journal, 110-111:1:12, (January 1941).

444. Plumbing and Public Health. Kentucky Bulletin of the Department of Health, 12:6:125, (January 1940).

PETTIBONE, DOROTHY, BOGART, FRANKLIN B. and CLARK, PAUL F.:

445. The Bacteriology of the Bubble Fountain. Journal of Bacteriology, 1:5:471, (September 1916).

PRINCE, W. G.:

446. Practical Sanitation. The Plumber and Journal of Heating, 68:812:188, (September 1946).

447. Practical Sanitation.. The Plumber and Journal of Heating, 68:815:272, (December 1946).

448. Practical Sanitation. The Plumber and Journal of Heating, 68:816:302, (January 1947).

PUBLIC HEALTH SERVICE, U. S.:

449. Public Health Hazards in Plumbing. Pamphlet, 37 pp. (December 1937).

450. Manual of Recommended Water Sanitation Practice. Public Health Bulletin 296, United States Public Health Service, (1946).

PUTNAM, WALTER:

451. Possible Pollution of Water Through Use of Toilet Flush Valves. Journal, California Sewage Works Association, 5:1:106, (1932-1933).

RADCLIFF, J. D.:

452. Can Faulty Plumbing Cause Polio? Plumbing and Heating Business, 5:6:16, (January 1943).

RADDER, NORMAN J.:

453. Obsolete Plumbing May Mean Unsuspected Hazards. Buildings and Building Management, 34:5:41, (April 1934).

454. Plumbing Modernization from the Standpoint of Health. Buildings and Building Management, 35:2:84, (January 16, 1935).

455. Cross Connections in Plumbing. Hotel Management, 37:264, (April 1935).

456. Modern Toilet Rooms. Buildings and Building Management, 38:2:66, (January 16, 1938).

457. Health in the Schools Sanitation First. The Nation's Schools, 25:2:45, (February 1940).

458. Maintaining the Plumbing. Buildings and Building Management, Directory Issue, 42:60, (January 16, 1942).

459. Check List for School Heating and Plumbing. Nation's Schools, 29:5:41, (November 1943).

460. Health in the School, The Maryland Master Plumber, 15:2:12, (August - 1940).

RAWLINGS, I. D. and FERGUSON, H. F.:

461. Responsibilities of Municipalities, Water Companies and Individuals for Water Borne Illness. Journal, American Water Works Association, 16:415, (October 1926).

REEVES, HUBERT A.:

462. Correctly Designed Water Pipes: A Safeguard Against Back Siphonage. Western Plumbing and Heating Journal, 19:227:5, (November 1938).

REICHMAN, IRVING:

463. Backflow Preventer Installations. Journal, APHA, 34:10:1093, (October, 1944).

REYNOLDS, C. H.:

464. Cross Connections and Back Siphonage in Plumbing and Drainage Systems, Maryland Master Plumber, 15:8:4, (February 1941).

RICE, J. W.:

465. Amebic Dysentery. Journal, Pennsylvania Water Works Operators' Association, 6:60, (1934).

RIKER, I. RUSSELL and NICHOLS, CHARLES M.:

466. Physical Connections to Public Potable Water Supply Systems in New Jersey. New Jersey State Department of Health, Health News, 14:3:4:68, (February and March 1929).

ROBERTS, F. C., JR.:

467. Protection from Water Closet Cross Connections. Arizona Public Health News, No. 113, (July 1935).

RODIEK, M.:

468. Rohrbelüfter (Rohrunterbrecher) als schutz der reinwasser leitungen gegen rücksaugen. (Siphon breakers as a protection of the water supply line against back siphonage). Dad Gas-und Wasserfach, 78:949, (December 21, 1935).

ROSS, OSCAR A. and HITCHENS, ARTHUR PARKER:

469. Bubbling Drinking Fountins, Journal, American Water Works Association, 35:165, (February 1943).

ROSS, ROBERT M.:

470. Cross Connections in a Soda Fountain. Domestic Engineering, 131:3:75, (May 3, 1930).

SCHULZE, MILLER H. and REYNOLDS, C. H.:

471. An Educational Program for the Prevention and Elimination of Cross Connections in Baltimore. Proceedings, American Society of Sanitary Engineering, 17:874, (1933-1935).

472. Cross Connections: A Potential Menace to Health. Maryland Master Plumber, 9:8:5, (January 1935).

473. The Prevention and Elimination of Potential Cross Connections in Plumbing Installations. Proceedings, 10th Annual Conference, Maryland-Delaware Water and Sewage Association (1936).

SCOTT, WARREN J.:

474. Cross Connections in Connecticut. Journal, New England Water Works Association, 41:365, (December 1927).

475. How to Make Cross Connection Surveys. Journal, New England Water Works Association, 49:354, (December 1935).

476. Responsibility for Water Piping on Consumer Premises, Journal, New England Water Works Association, 59:60, (March 1945).

SELIGMAN, FELIX:

477. Plumbing Cross Connections. Proceedings, Minnesota Section, American Water Works Association, p. 3, (August 24-25, 1939).

SHAW, W. E.:

478. Cross Connection Control and Elimination in California. Journal, American Water Works Association, 37:5:1159, (November 1945).

SHENTON, H. C. H.:

479. The Modern Trend of Sanitary Engineering as Affecting Public Buildings. The Surveyor (London), 91:557, (April 16, 1937).

SHERMAN, L. K.:

480. Plumbing Fixtures Subject to Back Siphonage. Journal, New England Water Works Association, 51:266, (September 1937).

481. Checking Indoor Water Pollution. Connecticut Health Bulletin, 52:2:43, (February 1938).

482. Connecticut's New Plumbing Regulations as Affecting Water Supplies. Journal, New England Water Works Association, 52:351, (September 1938).

483. Protection of Public Water Supply Systems From Pollution by Cross Connection and Back Siphonage. Connecticut Bulletin of Health, 55:329, (December 1941).

SIEMERS, H. J.:

484. Sanitary Plumbing. The Sanitarian, 2:2:9, (July 1939).

SLANE, NORMAN F.:

485. Cross Connections Present Another Problem for Sanitarians. The Sanitarian, 2:8:9, (January 1940).

SPENCER, WALTER:

486. The Plumber and Public Health. State Board of Health. Bulletin, Wisconsin, 6:18:6, (April-June, 1940).

STANDARDS, BUREAU OF:

487. Recommended Minimum Requirements for Plumbing in Dwellings and Similar Buildings, (July 3, 1923).

488. Report of Sub-Committee on Plumbing of the Building Code Committee. Recommended Minimum Requirements for Plumbing. Washington, D. C., 283 pp. (March 5, 1932).

489. Building Materials and Structures, Report BMS 66, Plumbing Manual, Report of Sub Committee on Plumbing, Central Housing Committee on Research, Design and Construction. National Bureau of Standards, United States Department of Commerce, (November 22, 1940).

STARBUCK, R. M., JR.:

490. Dangers of Cross Connections. Domestic Engineering, 127:6:53, (June 15, 1929).

491. Has Plumbing Any Relation to Public Health? Domestic Engineering, 132:6:85, (September 1930).

492. Sanitary Connections for Bars. Domestic Engineering, 143:141, (March 1934).

STATE SANITARY ENGINEERS, CONFERENCE OF:

493. Report of Committee on Cross Connections. Transactions, 10th Annual Conference, p. 35, (September 1929).

494. Essential Features in Design of Sanitary Drinking Fountains. Transactions, 13th Annual Conference, p. 55, (October 1932).

STEELE, FRANK:

495. Preventing Heating Boiler Explosions. Plumbing and Heating Journal, 116:9:42, (September 1945).

STERNS, M. M.:

496. The Hazard of Faulty Plumbing. Survey Graphic, 28:6:382, (June 1939).

STEVENS, E. F.:

497. Hospital Sanitation Equipment. Architectural Forum, 57:5:461, November, 1932.

STINE, L. B.:

498. The Safeguarding of our Health. The Valve World, 29:9 and 10:165, (September and October, 1932).

499. Importance of good Plumbing Properly Installed. The Valve World, 33:1:17, (January 1936).

STOCKTON, EDWARD LEE:

500. Cross Connection Survey in Calhoun County, Michigan (A Special Study Submitted in Partial Fulfilment of the Requirements for the Degree of Master of Science in Civil Engineering in the Graduate School of the University of Missouri, June, 1942, The University of Missouri, Bulletin No. 31, 1942.

SULLIVAN, E. J.:

501. Cross Connections and the Plumbing Testing Laboratory in the New Bedford Vocational School. Journal, New England Water Works Association, 54:2:179, (June, 1940).

502. Siphonable Plumbing Fixtures in Common Use at State Institutions. Progress, 2:12:11, (August 1940).

SWANSON, A. W.:

503. Camera Helps Inspector Enforce Plumbing Law. Plumbing and Heating Trade Journal, 101:4:50, (October, 1936).

TAYLOR, STEPHEN H.:

504. Water Department Regulation of Pipes Within Buildings. Journal, New England Water Works Association, 50:129, (June 1936); Water Works and Sewerage, 83:78, (March 1936).

505. Water Department Responsibility for House Water Supply Plumbing. Water Works Engineering, 89:275, (March 4, 1936).

THOMSON, T. N.:

506. Look Behind the Fixtures as You Modernize Plumbing. Plumbing and Heating Trade Journal, 97:4:43, (October 1934).

507. The Practical Application of Modern Plumbing Specialities. Plumbing and Heating Trade Journal, 103:3:98, (September 1937).

TOLAN, G. J.:

508. Cross Connections and Their Public Health Significance. North Dakota Water and Sewage Works Conference, Official Bulletin, 2:11, (June 1936).

TYLER, R. G.:

509. Cross Connections in Plumbing as a Health Menace. Publications, Massachusetts Institute of Technology, 65:45, (1929).

UNDERWOOD, W. B.:

510. Textbook of Sterilization. American Sterilizer Company, Erie, Pa., p. 116, (1934).

VINCENZ, J. L.:

511. Field Experiments in Problems of Water Contamination from Private Flush Valves. Journal, California Sewage Works Association, 5:110, (1932-1933).

WALTERS, H. H.:

512. Plumbing Defects: Administrative Aspects. The Plumber and Journal of Heating, 70:831:38, (April 1948).

WARING, F. H.:

513. Proper Water Supply and Drainage Piping for Hotels. Journal, American Water Works Association, 28:242, (February 1936).

WECKWERTH, F.:

514. Sicherungen der trinkwasserleitungen gegen rücktritt von warm- und abwasser. (Protecting the drinking water from contamination). Das Gas-und Wasserfach, 78:687, (September 7, 1935).

WESTON, ARTHUR D. and GETING, VLADO A.:

515. The Importance of Plumbing in Public Health, Progress, 6:9:8, (May 1944).

WHITE, H. L.:

516. Cross Connection and Plumbing Fixtures Studies. Journal, American Water Works Association, 25:922, (July 1933).

WHITTAKER, H. A.:

517. Drinking Fountains: Investigations of Fountains at the University of Minnesota. Public Health Reports, 32:19:691, (May 11, 1917).

WILEY, JOHN S.:

518. Industrial Sanitation in Indiana, Indiana State Board of Health. Monthly Bulletin, 42:128, (June 1939).

WILSON, C. M.:

519. Sanitary Facilities of the Future. Architectural Record, 81:42, (January 1937).

WILSON, E. CLEM:

520. Back-Siphonage of Flush Valves: Causes and Remedies. Pamphlet (February 1935).

WOLMAN, ABEL:

521. Vertical Towns. (Editorial). Municipal Sanitation, 5:45, (February 1934).

522. Defective Plumbing (Editorial). Municipal Sanitation, 6:291, (October 1935).

WOLMAN, ABEL and FORMAN, ARTHUR E.:

523. The Significance of Waterborne Typhoid Fever Outbreaks, 1920-1930. Journal, American Water Works Association, 23:160, (1931).

WOLPERT, M. M.:

524. When Good Water Becomes Bad. Water Works Engineering, 86:586, (June 14, 1933).

525. Disease-Spreading Installations. Water Works Engineering, 86:633 and 678 (June 28 and July 12, 1933).

526. Controlling Cross Connections. Water Works Engineering, 86:728, (July 26, 1933).

527. Piping Sickness to Consumer. Water Works Engineering, 86:779 and 823, (August 9 and 23, 1933).

ZINKIL, R. H.:

528. Value of a Testing Laboratory in Development of Plumbing Fixtures. Proceedings, American Society of Sanitary Engineering, 17:81, (1933-1935).

529. Safe Air-gaps to Prevent Back Siphonage. The Valve World, 33.4:133, (October 1936).

530. Liberal Size Piping Provides the Answer to Many Back Flow Problems, Plumbing and Heating Business, 1:3:29, (November 1938).

531. Combating Backflow in Water Supply Systems, Journal, New England Water Works Association, 53:4:458, (December, 1939).